

This certifies that the Quality Management System of

Windsor Laser Cutting Inc.

5500 Dicocco Ct. Oldcastle, Ontario, N0R 1L0, Canada

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

ISO 9001:2015

Scope of Certification:

Laser Cutting, Fabricating, Machining and Coating of Metal Products with one (1) additional manufacturing location at 1625 Rossi Drive, Windsor, Ontario N9A 6J3, Canada.

8

Sameer Vachani Senior Director, NSF-ISR Certificate Number:C0205144-IS5Certificate Decision Date:18-APR-2023Certificate Issue Date:01-MAY-2023Cycle Effective Date:17-MAY-2023Certificate Expiration Date*:16-MAY-2026







Certificate of Registration

ANNEX PAGE FOR CERTIFICATE NUMBER: C0205144-IS5

This Annex is only Valid in connection with the above-mentioned certificate issued by NSF-ISR

CERTIFICATE ISSUE DATE: 01-MAY-2023 **CERTIFICATE EXPIRATION DATE:** 16-MAY-2026

Windsor Laser Cutting Inc. 5500 Dicocco Ct. Oldcastle, Ontario, N0R 1L0, Canada Location: Windsor Laser Cutting Inc.-C0734466

1625 Rossi Drive

Windsor, Ontario, N9A 6J3, Canada

Location:

Windsor Laser Cutting Inc.-C0205144 5500 Dicocco Ct. Oldcastle, Ontario, NOR 1L0, Canada

Scope:

This location is part of site: C0205144 Supporting processes include: laser, paint, final assembly and shipping

Scope:

Laser Cutting, Fabricating, **Machining and Coating of Metal** Products.

Issued by: NSF International Strategic Registrations (NSF-ISR) 789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.





